


- TRAFFIC CONTROL POINTS:**
- TCP-1: AT THE MAIN ENTRANCE TO HERSHEY MILL VILLAGE
  - TCP-2: AT THE INTERSECTION OF GREENHILL ROAD AND HERSHEY MILL ROAD
  - TCP-3: 100 FT WEST OF CHANDLER DRIVE AND JEFFERSON WAY IN HERSHEY MILL VILLAGE
  - TCP-4: 300 FEET EAST OF CHANDLER DRIVE AND PRINCETON LANE IN HERSHEY MILL VILLAGE
  - TCP-5: AT INTERSECTION OF CHANDLER DRIVE AND DEVON WAY IN HERSHEY MILL VILLAGE
  - TCP-6: 1000 FEET WEST OF INTERSECTION OF CHANDLER DRIVE AND DEVON WAY IN HERSHEY MILL VILLAGE



- REFERENCES:**
1. FEMA FLOOD INSURANCE RATE MAP (FIRM) FOR CHESTER COUNTY, PENNSYLVANIA, PANELS 160 AND 215 OF 380, MAP NUMBERS 42029C0160F AND 42029C0215F, MAPS REVISED SEPTEMBER 29, 2006
  2. FEMA FLOOD INSURANCE STUDY (FIS) FOR CHESTER COUNTY, PENNSYLVANIA, VOLUME 1 AND 3 OF 3
  3. FIELD REVIEWED BY YERKES ASSOCIATES, INC.

1	JAN 06, 2009	PER PADEP
NO.	DATE	REVISION COMMENT
<b>FLOOD INUNDATION MAP</b>		
<b>EAST GOSHEN TOWNSHIP</b>		
PREPARED FOR		
<b>HERSHEY'S MILL DAM DEP NUMBER D15-125</b>		
East Goshen Township • Chester County • Pennsylvania		
<b>Yerkes</b>		
<b>YERKES ASSOCIATES, INC.</b>		
CONSULTING ENGINEERS	LANDSCAPE ARCHITECTS	
SITE PLANNERS	SURVEYORS	PROJECT - W-07-4058-12 DATE - August 30, 2007 SCALE - 1" = 300' DRAWN - MDC CHECKED - WPH CAD FILE W-07-4058-12 R1.pro TAX PARCEL - 53-2J-13.1 NOTEBOOK - PLAN NO.
1444 PHOENIXVILLE PIKE • P.O. BOX 1568 • WEST CHESTER, PA 19380 TEL: (610) 644-4234 • FAX: (610) 640-0771		<b>C-53-2J-13.1</b>
		<b>SHEET 1 OF 1</b>