



DEP DATA RECORDS	Inspection #
Complaint #	Enforcement #
Dam #	Date

**COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF WATERWAYS ENGINEERING  
DIVISION OF DAM SAFETY**

**DAM SAFETY INSPECTION NOTICE**

DEP Office Address	Southeast Regional Office 2 East Main street Norrstown, PA 19401	Phone 484-250-5970	Dam Permit or I.D. # <b>D15-125</b>
Owner or Permittee	<b>Louis F. Smith Jr. Manager</b>		Dam or Project Name: <b>Hershey Mill Dam</b>
Complete Mailing Address	<b>East Goshen Township 1580 Paoli Pike West Chester, PA 19380-6199</b>		County: <b>Chester</b>
			Municipality: <b>East Goshen Township</b>
			Stream: <b>Ridley Creek</b>
			Take GPS readings at the center of the crest of the dam.
			Latitude: ° ' " North
			Longitude: ° ' " West

Type of Inspection: ADMIN – Administrative/File Review      CONST – Construction Progress      FLWUP – Follow up  
 CEI – Compliance Evaluation      ■ DAM12 – Category 1 or 2 dam      INCDT – Incident response  
 COMPL – Complaint inspection      DAM3 – Category 3 dam      OTHER

Location/Appurtenance	Insp.	Condition		Comment/Explain Concern	Violation Check if yes	Cite 25 Pa. Code
		OK	Concern			
Crest	■		■	Over grown, inspection not possible		
Upstream Face	■		■	Over grown, inspection not possible		
Downstream Face	■		■	Over grown, inspection not possible		
Outlet Structure	■	■				
Outlet Conduit	■					
Primary Spillway	■	■				
Emergency Spillway	■		■	Over grown, inspection not possible		
Spillway Channels	■	■				
Downstream Toe Area	■		■	Over grown, inspection not possible		
Encroachments						
Site Restoration						
E & S Plan on Site						
E & S Controls						

Inspection Results Code:	■ NOVIO (No significant violations noted)	OUTST (Outstanding violations, notice req'd)	RECUR (Recurring violations)	REPAR (Repairs or upgrade required)
	VIOIC (Viols noted and immediately corrected)	VIOLS (Violation(s) noted)	VOV (New and outstanding violations noted)	VRV (New and recurring violations noted)
	DVN (deminimus violations noted)			

Violations Noted? Yes ■ No      Field Notice of Violation? Yes No      Compliance Order? Yes No

Remarks: This report is a summary of the undersigned DEP representative's brief visual inspection only on this date, not an in-depth investigation of the dam's present condition or compliance history. The condition of the dam can change rapidly, particularly with changes in reservoir level and changes in weather conditions. The inspector's full report is available by contacting the DEP office noted above.

- 1) Dam is not maintained and is in poor condition.
- 2) Due to dense woody vegetation, inspection of dam components is not possible. Remove all trees including stumps from crest, upstream, and downstream faces. Areas should be properly backfilled and then reseeded.
- 3) Drawdown system is not operable, requires repairs.
- 4) All eroded areas along the crest, upstream and downstream faces should be properly stabilized.

DEP Inspector was accompanied by	DEP Rep:	Date:
Owner	Engineer for Owner or Permittee (signature) <i>Govind Daryani</i>	6/12/08
Permittee	Other (print name) Govind Daryani Phone: 484-250-5165	Time:

■ White – Owner, Permittee, or Representative      ■ Yellow – Division of Dam Safety, Central Office      Pink – DEP Regional File